QUALITY CONTROL

Name of the Work:	Filling of Potholes in Arterials and sub-Arterials and sub-Arterials roads in dasarahalli Ward no 15 T Dasarahalli Sub-
Job No:	015-13-000062
Work order No:	125/13-14 D:29.08.2013
BR No:	661/31.10.2014

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed Two years back.

Assistant Executive Engineer
Dasarahalli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike